



## Glass Vice® Powder Coated Vices Care & Maintenance

To maintain the appearance and protective properties of your powder coated surfaces you need to routinely clean the surface to remove dirt and grime.

All you need is a gentle clean with a soft brush and mild detergent, followed by a fresh water rinse.

In normal environments cleaning should occur every 12 months, in coastal areas or environments, cleaning should occur every 3 months.

In beachfront, marine environments cleaning should be increased to monthly.

*Create a Clear Vision*